
P-0080A-00 AFT WIRING HARNESS TOW 2B 08-20-91

PART NAME: AFT WIRING HARNESS

PART NUMBER: 13367020

UNIT PACKAGE QUANTITY: ONE PART PER UNIT CONTAINER.

CUSHIONING: CELLULOSIC MATERIAL, FLEXIBLE FOAM, AIR-CAP OR EQUIV.
DO NOT USE SHREDDED PAPER.

UNIT CONTAINER: TRANSPARENT, FLEXIBLE, POLYETHYLENE BAG, MINIMUM OF
.0015 THICK.

PACKAGING METHOD: PREVENT R1 RESISTOR ASSEMBLY (BREAKOUT 1 ON THE
DRAWING) FROM BENDING BY FOLDING CORRUGATED, OR PAPERBOARD OVER THAT
SECTION OF THE HARNESS. COIL THE REMAINING HARNESS AND PLACE INTO
BAG. STAPLE OR TAPE THE BAG CLOSED WITH A MINIMUM OF ENCLOSED AIR.
PLACE ANY NUMBER OF UNIT CONTAINERS INTO AN INTERMEDIATE CONTAINER,
WHICH IS A FOLDING BOX, SETUP BOX, OR A CORRUGATED FIBERBOARD BOX.
PROTECT PARTS ADEQUATELY, AND FILL VOIDS WITH CUSHIONING. A MAXIMUM
GROSS WEIGHT OF 40 POUNDS IS RECOMMENDED, BUT DO NOT EXCEED WEIGHT
LIMITATIONS OF CONTAINER.

SHIPPING CONTAINER: CORRUGATED FIBERBOARD BOX, DOMESTIC, RSC, OF
SUFFICIENT QUALITY AND STRENGTH TO INSURE SAFE ARRIVAL OF PARTS.

PACKING METHOD: PACK ANY NUMBER OF INTERMEDIATE CONTAINERS INTO A
SHIPPING CONTAINER. A MAXIMUM GROSS WEIGHT OF 40 POUNDS IS
RECOMMENDED, BUT DO NOT EXCEED WEIGHT LIMITATIONS OF CONTAINER.
FILL VOIDS WITH CUSHIONING OR EMPTY INTERMEDIATE CONTAINERS

MARKING INSTRUCTIONS: EACH UNIT BAG MUST BE MARKED WITH HAC PART
NUMBER AND QUANTITY. UNIT CONTAINERS ARE EXEMPTED FROM MARKING ONLY
IF HAC P/N IS VISIBLE ON PART.

PALLETIZATION: IF REQUIRED, PALLETIZE WITH ANY STANDARD PALLET SUCH
THAT A STABLE, UNITIZED, AND STACKABLE LOAD IS CREATED. FIBREBOARD
(CARDBOARD) PALLETS WITH PLASTIC CUP FEET ARE NOT ALLOWED.

NOTE: TO PRESERVE THE ENVIRONMENT, RAYTHEON CO. RECOMMENDS
THAT PACKAGING MATERIALS WHICH ARE MANUFACTURED FROM, AND OR, WITH
CFC'S (CHLOROFLOORCARBONS) NOT BE USED.

THIS ATTACHMENT, WITH ITS TERMS AND CONDITIONS, IS AN INTEGRAL PART
OF THIS PURCHASE ORDER.

* REVISION

6042V